

# Reprocessing Instruction in accordance with ISO17664

### Air Motor

#### Preparation 1



- ⚠ Automated cleaning can only be performed on the FX205m / S-Max M205.
  - · After cleaning remove any remaining moisture using a dry cloth or compressed air ensuring it is dry internally and externally.
  - · Cover the product with a cloth when drying with compressed air to prevent water aerosol from being produced.
  - Use a nationally approved disinfectant with proven bactericidal, fungicidal, and virucidal properties.

## 3 Lubrication



#### 4 Packaging, Sterilizing and Drying





Use a sterilization pouch that conforms to ISO 11607-1. Seal the pouch. Maximum temperature for NSK instruments is 135°C.

Perform steam sterilization using the conditions above. Use a steam sterilizer to perform sterilization.

#### 5 Storage



NAKANISHI INC. 🖬 700 Shimohinata, Kanuma, Tochigi 322-8666, Japan



Steam sterilization

EO

**[**•\*

Plasma